
Jle

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340

Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	Gene	eneral Information	
	1.	Report Time Period: From (mo./yr.) $01/93$ To (mo./yr.) $12/93$	
	2.	DOGM File Number (Mine No): M / 017 / 001	
	3.	Mine Name: Lucky Strike/ Tony M	
	4.	Mineral(s) Mined (or permitted to mine): Uranium	
	5.	Type of mine	
	6.	Legal Description (Location of Lands Affected):	
		SE 1/4, SW 1/4, Section $\frac{16}{}$, Township $\frac{35}{}$, Range $\frac{11}{}$	
		NE 1/4, NW 1/4, Section 21 , Township 35 , Range 11 .	
		NW 1/4, NE 1/4, Section 21 , Township 35 , Range $11E$	
	7.	Name of Operator or Company: Nuclear Fuel Services, Inc.	
	8.	Permanent Street Address: 3945 Holcomb Bridge Road, Suite 202	
		City, State, Zip: Norcross, Georgia 30092	
		Phone: (404) 662-8405	
	9.	Company Representative (or designated operator):	
		Name: Jay M. McMurray	
		Title: Senior Consultant	
		Business Address: Nuclear Assurance Corporation	
		City, State, Zip: 9940 Costilla Avenue, Suite B, Englewood, CO 80112	
		Phone: (303) 792-2462	
		Please check if any of the above information has changed since previous year.	
II.	Minin	g and Reclamation	
	1.	Was the mine active during the past year? Yes ☐ No 🖾	
	2.	If active, how much ore or mineral was mined? N/A	

	 How much additional acreage was disturbed during the past year? None Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work
	performed, and volume of material moved.
	None
5.	How much acreage was reclaimed during the past year? less than one acre
6.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
	Initiated underground storage tank remediation. A portion of the
	contaminated soil was removed and composted. Work is ongoing.
7.	What is the total disturbed acreage at years end? Approximately 52 acres
8.	Briefly summarize any mining and/or reclamation plans for the upcoming year. None
	NOTE
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .
III. Additio	nal Information
1.	An updated surface facilities map should be attached if there have been significant changes since previous map was submitted.
2.	Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.
IV. Signat	ure Requirement
I he	reby certify that the foregoing is true and correct.
	Name (Typed or Print): Paul F. Schutt
	Title of Operator: Chief Executive Officer
	Signature of Operator:
	Date: 1/3/94
jb	/ /